

Update on Site Supervision requirements

H. Kennedy



Objective


“Clearly set out the role of the Contractors’ Site Supervisors on IDD projects, outlining the minimum requirements for the person(s) fulfilling the role”

- To address an identified common root cause of incidents and HiPo’s




Infrastructure HSQE Dashboard – December 2023

Incidents Reported December YTD 2023 Root Cause



New Frontline Supervision Structure



Role	Works Supervisor (WS) Stage 1	Person in Charge of Works (PICW) Stage 2
Responsibilities:	Responsible for ensuring RAMS are followed	Responsible for safety of personnel on site and risk assessment
Site Presence:	On site at all times during works	On site at least once daily
Operative/Crew Limits:	Max 8 Operatives : 1 WS	Max 5 Crews : 1 PICW Max 15 Operatives : 1 PICW
Min. Site Mgmt Training:	2-Day CIF City & Guilds <u>or Equivalent</u>	5-Day CIF IOSH
Appointed by:	PSCS	PSCS
Directly Employed by:	PSCS/Main Contractor/Subcontractor	PSCS/Main Contractor